


Super Strat wiring diagram

Darkmoon Pickups®

<https://darkmoon.nyc/>



 - Solder joint

*All bare wired from pickups go to ground